Dart Aerospace Ltd. Wednesday, 5/31/2006 7:40:20 AM Kim Johnston **Process Sheet** : CU-DAR001 Dart Helicopters Services **Drawing Name** : SHORT STEP INSTALLATION KIT Customer Job Number : 27308 : 10542 **Estimate Number** : K591113 Part Number MIH: P.O. Number S.O. No. : NIX : D350-591 REV F PG17 **Drawing Number** : 5/31/2006 This Issue : N/A **Project Number** : NC Prsht Rev. : NIA : SMALL /MED FAB Type Drawing Revision First Issue : NIA : 27046 **Previous Run** Material Each Due Date : 6/30/2006 Qty: 6 Um: Written By Checked & Approved By Reformat KJ/JLM Comment **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** Clamp 1.0 D2171 Comment: Qty.: 2.0000 Each(s)/Unit Total: 12.0000 Each(s) Clamp Pick: Qtv Part Number Description 2 D2171 Clamp 2.0 D2182B Comment: Qty.: 0.5833 f(s)/Unit Total: 3.4998 f(s) Neoprene Cushion-.750 bl Pick: Description Batch Qty Part Number 7"(2 x 3.5") D2182B Cushion Radius Block 3.0 D2274 4.0000 Each(s)/Unit Total: Comment: Qty.: 24.0000 Each(s) Radius Block Pick: Description Qty Part Number Radius Block 4 D2274 4.0 D23623 Step Support Bracket Comment: Qty.: 1.0000 Each(s)/Unit Total: 6.0000 Each(s) Step Support Bracket

Page 1

Pick: Qty

Part Number

D2362-3

Description

Support Bracket

16 06/06/10

## **Dart Aerospace Ltd**

W/O:			WC	ORK ORDER CHANGES						
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву		Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
								1	<u></u>	<u> </u>
NCR:			WORK ORD	ER NON-CONFORMANO	CE (N	CR)				
DATE	STED	Description of NC		Corrective Action Section B			Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr		n & ate	Secti		Design Mgr	QC Inspector
	,									
									<u> </u>	
·										
Part No	);	PAR #:	Fault Categor	y: NCR: Y	es N	o <b>D</b>	QA: _		Date:	
NOTE: D	ate & initia	al all entries	_		(A: N/C				Date:	

Date: Wednesday, 5/31/2006 7:40:20 AM Kim Johnston User: **Process Sheet** Drawing Name: SHORT STEP INSTALLATION KIT Customer: CU-DAR001 Dart Helicopters Services Job Number: 27308 Part Number: K591113 Job Number: Description: Seq. #: **Machine Or Operation:** Abrasion Strip 5.0 D2856400 Comment: Qty.: 0.6000 f(s)/Unit Total: 3.6000 f(s) Abrasion Strip Pick: Qty Part Number Description Abrasion Strip 7.2" D2856-400 AN337A 6.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 12.0000 Each(s) Bolt Pick: Qty Part Number Description 2 AN3-37A Bolt 7.0 AN420A Comment: Qty.: 4.0000 Each(s)/Unit Total: 24.0000 Each(s) Bolt Pick: Description Qty Part Number AN4-20A Bolt 4 8.0 AN422A Comment: Qty.: 1.0000 Each(s)/Unit Total: 6.0000 Each(s) Bolt Pick: Qty Description Part Number AN4-22A Bolt AN960JD10 9.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 24.0000 Each(s) Washer Pick: Qty Part Number Description AN960JD10 Washer 4

## Dart Aerospace Ltd

	WORK ORDER O	HANGES				
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
	STEP		STEP PROCEDURE CHANGE By			STEP PROCEDURE CHANGE By Date Qty Mfg / Design

NCR:			WORK ORDI	ER NON-CONFORMANC	E (NCR)	1 1 10 10 10 10 10 10 10 10 10 10 10 10		
		Description of NC		Corrective Action Section B			Approval	Approval
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date		Approval Design Mgr	QC Inspector
					;			
	<u></u>						L	

				1 .			
Part No:	PAR #:	Fault Category:	NCR:	Yes No D	QA:	Date: 🖔	107/11
NOTE: Date & initi	al all entries			QA: N/¢ Clos	ed:	Date:	
				;			

Wednesday, 5/31/2006 7:40:21 AM Date: User: Kim Johnston **Process Sheet** Drawing Name: SHORT STEP INSTALLATION KIT Customer: CU-DAR001 Dart Helicopters Services Part Number: K591113 Job Number: 27308 Job Number: Seq. #: Description: **Machine Or Operation:** AN960JD416 Washer 10.0 Total: 36.0000 Each(s) Comment: Qty.: 6.0000 Each(s)/Unit Washer Pick: Qty Part Number Description 6 AN960JD416 Washer 11.0 MS21042L3 Comment: Qty.: 12.0000 Each(s) 2.0000 Each(s)/Unit Total: Nut Pick: Qty Description Batch Part Number 2 MS21042L3 Nut MS21042L4 12.0 Comment: Qty.: 5.0000 Each(s)/Unit Total: 30.0000 Each(s) Nut Pick: Qty Part Number Description MS21042L4 5 Nut INSPECT 100% KITS FOR COMPLETENESS 13.0 QC4 Comment: INSPECT KITS 100% FOR COMPLETENESS PACKAGING RESOURCE #1 PACKAGING 1 14.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: DOCUMENT CONTROL 15.0 DC Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion

Form: rprocess

Page 3

## **Dart Aerospace Ltd**

W/O:			WO	RK ORDER CHANGE	S			
DATE	STEP	PRO	OCEDURE CHAN	GE	Ву	Date Qty	Approval Mfg / Design Mgr	Approval QC Inspector
		·						
					ļ ļ			
			<u></u>					
NCR:		,	WORK ORDE	R NON-CONFORMAN	ICE (NCR	2)		***************************************
				Corrective Action Section B		_	<u> </u>	
DATE	STEP	Description of NC Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector
					'			
					:			
					1			
: : !								
Part No	);	PAR #:	Fault Category	: NCR:	Yes No	DQA:	Date:	
		al all entries	5.7		QA: N/C CI		Date:	

## 5. PARTS LIST

Qty -111A	Qty -113	Qty -115	Qty -117A	Qty -119	Qty -133	Part Number	Description
X	-110	-110	-1117	1,10	100	D350-591-111A	Heli-Access-Step ™, Long Step – High Skid
<b>├</b> ~	X				i	D350-591-113	Heli-Access-Step ™, Short Step - High Skid
H		x				D350-591-115	Heli-Access-Step ™, Short Step - Low Skid
<del></del>			X		<del></del>	D350-591-117A	Heli-Access-Step ™, Pre-Flight Step
			<del>  ^-</del>	X		D350-591-119	Heli-Access-Step ™, Long Step – Low Skid
l					X	D350-591-133	Heli-Access-Step ™, Aft Maintenance Step
	1					D2310	STEP ASSEMBLY (HIGH-SHORT)
1						D2311	STEP ASSEMBLY (HIGH-LONG)
		1				D2354	STEP ASSEMBLY (LOW-SHORT)
				1		D2355	STEP ASSEMBLY (LOW-LONG)
					_ 1	D2946-041	STEP ASSEMBLY (MAINTENANCE)
						D2171	CLAMP
4	2	2	2	2	ļ	D2171 D2182B035	CUSHION
4	2	2	2	2			MOUNTING LUG
					4	D2230-1 D2230-3	MOUNTING LUG
		<u> </u>			4		RADIUS BLOCK
8	4	4	4	4		D2274	SUPPORT BRACKET
			1			D2362-041	SUPPORT BRACKET
2	1			11		D2362-3	SUPPORT BRACKET
		1				D2362-5	· · · · · · · · · · · · · · · · · · ·
2	1	1	1	1	2	D2856-400-720	ABRASION STRIP MOUNTING PLATE
					11	D2945	MOUNTING PLATE
2	2	2		2		AN3-37A	BOLT
		~			2	AN4-7A	BOLT
		-			4	AN4-11A	BOLT
					8	AN4-14A	BOLT
8	4	4	4	4		AN4-20A	BOLT
1	1	1		1		AN4-22A	BOLT
4	4	4		4		AN960JD10	WASHER
10	6	6	4	6	14	AN960JD416	WASHER
2	2	2		2		MS21042L3	NUT
9	5	5	4	5	14	MS21042L4	NUT

	Description	Part Number	Qty -124	Qty -123	Qty -122	Qty -121
	Heli-Access-Step ™, Short Step – High Skid, LH	D350-591-121				X
	Heli-Access-Step ™, Short Step – High Skid, RH	D350-591-122			Х	
	Heli-Access-Step ™, Short Step – Low Skid, LH	D350-591-123		Х		
	Heli-Access-Step ™, Short Step – Low Skid, RH	D350-591-124	X			
	STEP ASSEMBLY (HIGH-SHORT, LH)	D2351-041				
	STEP ASSEMBLY (HIGH-SHORT, RH)	D2351-041				
	STEP ASSEMBLY (LOW-SHORT, LH)	D2356-041		1		
	STEP ASSEMBLY (LOW-SHORT, RH)	D2356-042	11			
-57.	MOUNTING LUG	D2230-1	1	1	1	1
5 CObA	MOUNTING LUG SHO	D2230-3	1	1	1	1
URN TO	ABRASION STRIP RET	D2856-400-720	1	1	1	1
NEERING	BOLT ENG	AN3-37A	2	2	2	2
OLLED COL	BOLT	AN4-13A	3	3	3	3
C AMENDMEN	WASHER ()NCON !!	AN960JD10	4	4	4	4
O AMENDMEN	WASHER SUBJECT	AN960JD416	6	6	6	6
OUT NOTICE	NUT WITH	MS21042L3	2	2	2	2
K ORDER	NUT WO NO. Z	MS21042L4	3	3	3	3

• COPYRIGHT © 1993 BY DART AEROSPACE LTD •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision:  ${f F}$ 

Date: 04.03.02